



ZINO 2 Update tutorials

Tutorial video link



https://youtu.be/MLU4xNgBl0E

1 Tool Installation ① Download ZINO Image tool ZINO2_UpgradeTools_v4.0.7 and unzip the file ② This tool includes multiple platform

ZINO2_UpgradeTools_v4.0	7 •	_	
S称	修改日期	类型	大小
Fedora	2020/1/15 19:02	文件夹	
MacOS	2020/1/15 19:02	文件夹	
🔓 Ubuntu	2020/1/15 19:02	文件夹	
📔 Windows	2020/1/15 19:02	文件夹	
ZINO2	2020/1/15 19:03	文件夹	

③ Install the related tool according to the PC system .Now take window7 64bit as example.

④ Run AmbaUSB-win64-Qt5-Win7-4.0.7-Setup.exe under ZINO2_UpgradeTools_v4.0.7\Windows\Windows7&Above,and prompt to install the driver during installation



(5) Select the next step and wait for the installation to complete.



(6) After the installation is compete, you will see this icon on the system desktop, indicating that the tool installation is complete.



2 Update Steps

① Power off the drone and make sure MicroUSB is not connected to the drone.

② Connect the computer and the drone with the Micro USB cable and press the square button above the SD card holder to power on the drone.

③ After the drone startup sound is played, release the square button and wait for the driver installation to complete.



④ Open AmbaUSB update tool ,the initial interface is as follows:

				08.		
Amburella Development Boards Lint		Board Infonation				
Np Type Mode Device Node Device Status Progress						
	Delivor Woder Unknow					
		HAC Address				
	Fire	are Program Parameter	rx (023)			
	CHER	CHES	0102	05		
	0814	0826	0524	78.6		
eard's Config: [dis.1012.000	× 🖉	print 0	x00100000 🖗 45x ·			
Finance	• .	Pind Verify	E Road PTD	$\mathbf{\Psi}$		
Language: Massical Rafith			Log Level: In	• •		
1 and a second secon	18901.bert8903					

(5) Step 1, click the right tab and select S5L(H2S/H22)

Ambarelia EVK Firmware Downloader	
Anharella Development Deards List	Jourd Infontion
Np Type Mode Device Node Device Status Progress	
51(H25(H22) USB BudD+001.DevdD+003 Ready Ø	Das 🛷 BaszD#002.DevID#00
	BC Mileres
	E32
	0x00100000 @ 5% 025/022 -
	Time
	CED Read PTB CE
	004 705
ioard's Config: [C:/Isars/saysos.yang/Insktop/IIEC_Spyrables/sy/0.7/IEC/configs/IEC abs	• (#1. Jind 0x00100000 @ 886 (#32/#22) •
Firmure:	• 🚜 Tint 🗹 Verify 🖉 Read 273
🕽 Langunge: 🎫 merican English 💌	Log Loval: Info ·
020-01-15-19:27:11.842; amba usb device.cpp[180]; Manufacturer: Amba 020-01-15-19:27:11.842; amba usb device.cpp[180]; Product: E2	
020-01-15-19:27:11.043; ambs unb device.cop/ 1801; Serial Number; 123456789ABC	
020-01-15-19:27:11.843; amba umb device.cpp[189]; UOB Mode 020-01-15-19:27:11.843; amba_umb_device.cpp[239]; Speed: HIGH	
020-01-15-19:27:11.843: ambs unb device.cpp[252]: MaxFower: 201mA 020-01-15-19:27:11.843: ambs unb data model.cpp] 3771: Found new Ambs 028 device: BusID#00:	
420-01-15-1512/111-0451 AMDA_HDB_BACA_HODE1-0001 5//11 FORMA BEV AMDA 400 BEVIDE1 BESIDE00.	01.00010000

If the device appears after selecting S5L(H2S/H22), which means connect successfully

crip type mode bevice node bevice status ringress					
SSL(H2S/H22) USB BusID#001.DevID#003 Ready		0%	٩		0 0 - 8
SSUH2S/H22I US8 BusID#001.DevID#008 Ready 🔮 🚳 🛞			_	DusID	001.DevID#003
		1.0	Address		
		Tirnesre Prop	ran Parameter	x (185X)	
	0350		10 L	CHER	(203
	CHD4		£05	0106	7887
Board's Cealig: 102.000.000		* #& find	0.0	00100000 @ 01L002/1920 •	
Firmente					
		* #6.7155	V Verify	and TTS	
🚺 Lupup: 🔳 lawina laglish 💌			V Yerify	lag Lord: An	
			2 Terify		6 x \$
toxor (Mananakaika) 100-01 (Mananakaika) 100-01-01-017111407 edia affarina cegi 1011: Manafarianani 101 100-01-01-017111407 edia affarina cegi 1011 Product 101 100-01-0147111400 edia affarina cegi 1011 Product 1010 100-01-0147111400 edia affarina cegi 1011 Product 1010 100-0140 100-0140 100-014 100-0			2 Yorify		•••

(6) Step 2, click the find button behind the Board' s config and select the path in the installation package ZINO2_UpgradeTools_v4.0.7\ZINO2\configs\ZINO2.ads

Ambarella EVK Firmware Downloader	08-2
Anhuralla Development Bourds List	Board Infonation
Chip Type Mode Device Node Device Status Progress	
531(H25/H22) USB BailD4001.DevID4003 Ready 🕴 0% 🚳	- Bis1D#001.Dev1D#00.
Seard's Config: [0://bers/exyses.yeg/Indelp/2582.3pg:oddirds.yet.0.1/2582/endig/2582.ods	Karinal K
	Firmware Program Farameters(0033)
	001 001 001 00
	004 005 004 115
See of a Centre (C./Tournington yeapTesting/TERC_Dynationalc.pt 0.1/22002/outr.pt/22002.etc	- 44,714 00010000 0 22.022/021 -
	• • • • • • • • • • • • • • • • • • •
🚯 Languago: 🚥 Anorican Raglish. *	Log Level: Info 💌 🍾
2012 01 01 01 01 01 01 01 01 01 01 01 01 01	bertägtet

⑦ Step 3, Click the Find button behind Firmware and select the path in the installation package ZINO2/firmware/ZINO2_IT_V0.4.3.elf



(a) Click the download button after choosing the file.

Anburella Development Fourds List	Jourd Infontion
Orip Type Mode Device Node Device Status Progress Stu(H25(H22) USB BudD+0012DwD+003 Ready Ø	Serial Rubber Hos See SwiID4001.DevID4003
	BC Milres
	Firmence Program Parameters (BEI)
	(100 (100 (100 (100
	2664
Board's Coafig: [://iners/mysm.ymg/Imit/sp/IIR2_Spyrad-mls_v4.0.7/IIR0/coafigs/IIR0.ads	- 7E57
Firmers C./Murs/super-pag/behtos/EEC./hgroidTody.vi.0.1/EEC/(reserv/EEC.31.00.4.3.4)	
Foreware: C./Ders/wyses.yaap/behtep/IIRC_bgrold/ols_v4.0.1/IIRC/firmer/IIRC_IL_0.4.3.df	- Matus
🚯 Language: Minerican English *	1: Inte • 🔪
2020-01-15-19:27:11.842: ambs_usb_device.cpp[180]: Manufacturer: Ambs	
2020-01-01-0107711.447 and and off-rise-copy 1101; Mannarcurren: Jahn 2020-01-01-05/07711.447 and such devices of 1101; Product 122 2020-01-01-05/07711.448; and such devices of 1101; Serial Manner: 12245/05002 2020-01-01-05/07711.448; and such devices.opt 1011; MSM Mole 2020-01-01-5/077711.448; and such devices.opt 2021; Speed: 8106 2020-01-01-5/077711.447; and such devices.opt 2021; Speed: 8106	
2020-01-15-19127111.8431 amba_usb_device.cpp[189]; USB Mode 2020-01-15-19127:11.8431 amba_usb_device.cpp[239]: Speed: BIGB	
<pre>2020-01-15-19127111.0431 Amin usb_device.cpp[252]: RearCover: 200mA 2020-01-15-19127:11.0431 ambs_usb_data_model.cpp[377]: Found new Ambs 008 device: BusID#001.DevID</pre>	Info 🔻 🏷
Ambarella FVK Firmware Downloader	
Anharella Development Deards List	Jourd Infontion
Chip Type Mode Device Node Device Status Progress	Serial Busber Nos Seo ResTigd01.RevTigd01
SSL(H25/H22) USB BuilD4001DevD4003 Start loading RLD Q	BASILWOOL.DEVIDWOOL BAC Address
	Timere Trepre Termeters(000)
	000 000 000 000 1151
	- 1200 2000 200 000 (00000000 - 1000 0000
Bowerd's Config: [C:/Tours/suppor.you/Toutop/IIRC_SpyroidTouts_V4.0.7/IB02/configu/IIRC.ols	
Firmware: C./Gows/mpsm.yaag/Sedstop/2000_Upg-addicals_pt-0.1/2200/firmware/2000_07_00-6.2.alf	→ #h Tist ? Yerity 3 tod 273
1 Language: Millionrina Inglish v	kog kovel: Tato 🔹 🍾
2223-01-15-13:34:44.233: amba_asb_device.cpp[877]: Boot modia is set to NAMD 2020-01-15-13:36:44.233: amba_asb_device.cpp[110]: NAL: C. (Program W.L.):ex/dahara:la/daha/232/chare/ambassh-4.0.7/nlaiform/33L/bld/ambhal.b	
2828-04.15-159.84.64.233: amb_umb_dvice.cpg[07]; Boot modia is set to NAMD 2020-04-15-109.84.42.233: amb_umb_dvice.pp[180]; BAL: c7/Popterm Filex/Amberdells/Ambe	10 send.bin
2320-01.1-01.510-01.41.233: and _usb_reture.cpg[077]: Nort media is net to XMMD 2320-01.1-01.510-01.41.233: and _usb_reture.cps[077]: Nort media is net to XMMD BLL C//Program files/Makerell/AmadeMD/AmatemMonther.d., 7/pintform/SL/MA/AD2_bLL DRADATA: Linkary C//Program Files/Makerell/AmadeMD/DLADATATATATATATATATATATATATATATATATATAT	0 aan.bin M.J.auf
283 di 1.5 19 19 19 19 19 19 19 19 19 19 19 19 19	0 0 mat.hin -4.1.012
2010 10.101 <th>n and Ann A A Juli</th>	n and Ann A A Juli
1210-011-013-014.211 (mdx, mdx, mdx, mdx, mdx, first to 1500 1210-01-011-014.211.211 (mdx, mdx, mdx, mdx, mdx, mdx, first to 1500 1210-01-011-014.211.211 (mdx, mdx, mdx, mdx, mdx, mdx, mdx, mdx,	in And San A dadaf Y
 Delle Li Schler, Sandar M. (2019). The second second	n Martina Martina M
🔿 Arbarela IVK Firmane Doorlaader	
∴ Arbards IVE Firmon Dourlader Advards Berch Lint	a D 🖝
🔿 Arbarela IVK Firmane Doorlaader	bret Islania Bret Balania Breta Balan Bo Boj
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Total Information Fourt Information Particul Patients Bernar Able: Balance RC Marco
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Incl Mathieu Constanting Const
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Total Information Fourt Information Particul Patients Bernar Able: Balance RC Marco
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Intel Intel Real Data Mark Real Data Mark <tr< th=""></tr<>
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Intel Identity
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Incl Matthew Real Matter State (Second Second Secon
≜ Antansis DV Finware Danslader Marcal L. Kontgenut Konste List Digs Figer Mick Denick table Denick Kana Troppes	Intel Identity
Andrech RV Streads Davidate	Evel Meansing Description Re thread Base Service Meansing Re thread Base Service Meansing Base Service Meansing Base Service Meansing Base Service Meansing Base Service Meansing Image Service Meansing Image Service Meansing
Andren's IV Fernan Gaussian	لا معالی استان الله الله الله الله الله الله الله ال
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	Interface Read Marching
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	See Shows See Shows <t< td=""></t<>
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	Interface Read Marching
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	Interface Read Marching
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	Interface Read Marching
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	Interface Read Marching
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	Interface Read Marching
Andrewis Ric Forman Dearlinker Marcella Rochmens Forein Kos Record Rochmens Forein Kos Record Rochmens Forein Kos Andrewis Rochmens Andrewis R	See Shows See Shows <t< td=""></t<>
Andrends RM formand Description Monocli & Rechargent France Kons Recharge Mark (Enderson Rechargent France Kons Recharge (Conservation Rechargence propriority) France & Society (Conservation Rechargence Propriority) Former (Conservation Rechargence Propriority) Former (Conservation Rechargence) Rechargence Rechargence Propriority Rechargence Rechargence Rec	See Shows See Shows <t< td=""></t<>
Andren's IV Fernan Gaussian	See Shows See Shows <t< td=""></t<>
Andrends RM formand Description Monocli & Rechargent France Kons Recharge Mark (Enderson Rechargent France Kons Recharge (Conservation Rechargence propriority) France & Society (Conservation Rechargence Propriority) Former (Conservation Rechargence Propriority) Former (Conservation Rechargence) Rechargence Rechargence Propriority Rechargence Rechargence Rec	Interface Read Marching
Andrends RM formand Description Monocli & Rechargent France Kons Recharge Mark (Enderson Rechargent France Kons Recharge (Conservation Rechargence propriority) France & Society (Conservation Rechargence Propriority) Former (Conservation Rechargence Propriority) Former (Conservation Rechargence) Rechargence Rechargence Propriority Rechargence Rechargence Rec	See Shows See Shows <t< td=""></t<>

				0 0
Amburella Development Boards List		Baard In	Emation	
No Type Mode Device Node Device Status Progress				
LIN25/N22) Amboot BuilD#001,Dev/D#000 Second				
		10C A	drann.	
		firmente Fregren	Fereneters (MX)	
	004	001	062	
	CREM	065	004	
we's Config: C./Recolourse.van/Testen/IISC./harolelesis.vi.0.1/IISC/configs/IDSC.eds		* #h Tist	0000100000 0000000000000000000000000000	
and a constant (Constant and a state of the				
Firmware: C. (See alwayse, read/below/2D82 New abilities vt. 0.7/2D82/Greener/2D82 II VI. 4.2. eld		*	write Read FTB	
				-
angenge: == #enrican Raglich -=			Log Lovel: In	(a
520-01-15-19:37:22.556: amba unb firmware sension.cpp1 1561: BasID#001.DevID#003 is removed!				í. •
22-01-15-19:37:22,556: ambs_sob_firmmarc_scension.cpp[156]: BasID#001.BevID#003 is removed! 250-01-15-19:37:34.739: ambs_sob_dwice_monitor_win32.cpp[131]: \\\\SBMVID_425s4FID_001#1234567#03DC#	(a5dcbf10-6530-11d	2-9015-00c04fb951e		(a •
22-0-1-10-15/57722.3-584: and and avia generation cpc[198]; BestD4001.Dev/D003 is removed: 10-0-1-1-19:17:34.738: and avia device generative viabl.cpc; 131]: \\\\SUBMYD_d12aVID_d12aVID_f0145244574500.C 10-0-1-1-19:17:34.738: and avia control of the second seco	(a5dcbf10-4530-11d	2-901f-90c04fb951e		4 •
3040-15-1571722.5494 sade, and Linnarcz pession cpp [189]: BoxID4001.BovID4001 is removed 1004-01-5-15917214-7894 sade, and device pentice yields.opp [11]: \\\Y\U0000000 (S054070_0014)22465740400 004-01-5-15917154-0184 sade, and device.copp [10]: Miniference: 20000 004-01-5-15917154.1894 sade and device.copp [10]: Miniference: 20000 004-01-5-15917154.1891 sade and device.copp [10]: Frontex: Raharcila 0200 prostic class 004-01-5-15917154.1891 sade and device.copp [10]: Strail Maderi 13464708400	(a54cbf10-4530-114	2-901f-90c04fb951e		6 V
20-01-15-1377722.3559: abb_usb_[IIImwire_mestion.epg] [16]: BastOHOI.Der[DHOI.Js removed] 20-01-15-137773-739: abb_usb_drive_mentery win32.epg] 131]: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	{a5dcbf10-4530-11d	2-9017-802047b951e		6 •
Sol 1-5 107172 3-81 mbc. mbc. 1092 (Transm. service cop) 18(1) host10401.ber(10001 is reserved. Sol 1-5 107172 3-81 mbc. mbc. 1092 (Transm. service cop) 18(1) host10401.ber(10001 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-81 mbc. 1092 (Service - 1091 is reserved. Sol 1-5 107171 3-	(a5dchf10-4530-11d	2-9012-90204fb951e		64 ¥
0 0	(a5dcbf10-4530-11d	2-501f-30c04fb851e		4 •
		2-9017-90c04fb951e		6 •
		2-9015-90204fb951e		64 · · ·
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		2-8012-802047b851e		£4 •
		2-9015-90c04fb951e		64 V
		2-9012-90c047b951e		fa •
		2-1015-20c04fb451e		(s •
20-01-15-1377722.3559: abb_usb_[IIImwire_mestion.epg] [16]: BastOHOI.Der[DHOI.Js removed] 20-01-15-137773-739: abb_usb_drive_mentery win32.epg] 131]: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		2-4017-40204fb451e		(s •
		2-8015-80c04fb851e		(<u>•</u> •
		2-4016-80204fb851e		<u>(, v</u>)
		2-1015-00204Tb951e		<u>(, v</u>)

⑨ Update completed.

	Anharella Develope	ent Beards List		3.	erd Infonat	i en		
No Tune Mode Device Node	Device Status	Progress						
SL(H25/H22) Amboot BuilD#001.DevID#0	d Success 🛛 🛛	200% 4			n www			
						•		
				Timere P		meters (MEX.)		
			700		000		CHEZ	
			0004		005		OTE	11
			0804		CHER		CHER	
erd's Cedis: C/Kers/seren vestin						0x00100000	● SSL (#3/102) ×	-
and a Coatig: [C/Issrs/sayson.yang/in	htsp/11802_SpgradeLoal	vvi 0.7/2180//endirge/2180/.nds		· · · · · · · · · · · · · · · · · · ·		0800100000	Contraction -	
								5
		1.94.0.7/IIRC/firmers/IIRC_II.80.4.3.41f			Verif.		Read 273	
Language: Minarican Baglish .	firmware mesalo	<pre>n.cpp[186]: BusID#001.DevID#003 is removed!</pre>			1		Lag Laval: Info	•
Language: Misserican Inglith	firmare sessio	n.cpp[156]: MusTD4051.DevTD4051 is removed! win52.cpp[121]: \\?\USD8VID_4255aFID_030181234	5476388C# (#5dcbd10-6630-11d2	10:00-1100	1		Log Lovel: Info	•
Language: Maserica Indith	firmunre messio device mesitor device.cpp[180	<pre>n.cpp[184]: BusID#001.DevID#000 is removed! wio3.cpp[121]: \\\\\USBWID_4255aFID_00181234 : Massificature: JABA</pre>	54783MBC# (#34:bf10-6530-1142	-5011-00:041	901ed)		Log Level: Info	•
Language: Menerica Indish	firmure sessio device menitor device.copf 180 device.copf 180	 a. cpp[186]; BasTBy001.BevTBy003 is removed! win52.cpp[121]; VVVUDWVTD_4235sTTD_000181234 BasTSciture: JMMA Protokni JMMArrila USB generio class 	54703ABC4 (#54:bf10-6530-1142	-5012-00c042	1		Log Lovel: Info	•
Language: Merrican English. * 20-01-15-19:27:22.556: anbh. an 20-01-15-19:77:34.735: anbh. an 20-01-15-19:77:34.356: anbh. an 20-01-15-19:77:34.356: anbh. an 20-01-15-19:77:34.356: anbh. an	firmware mention device monitor device.cpp[180 device.cpp[180 device.cpp[180	scpp[186]: BasID#001.DevID#0001is removed! win2ccpp[121]: \\\\UUD#VID_4255sTID_0001#128 : MasID_Former: MMA	54703MBC# (#54cbd10-4530-1142	5012-09c042	1		Log Lovel: Info	•
Lunguage: Milectical Indiate = 20-01-15-90:27:22.555; amba us 20-01-15-90:27:34.735; amba us 20-01-15-90:27:34.855; amba us 20-01-15-90:27:34.855; amba us 20-01-15-90:27:34.857; amba us 20-01-15-90:27:34.837; amba us	firmare sessio device_monitor device.cpp[100 device.cpp[100 device.cpp[160 device.cpp[160	 a. croft 1861; BastSp001. DevIDe000 1.s removed win37. croft 121; V.YVUUSBVID_4553.stD_010131254 Fastafacture: JABA. Profue: Jabarella UUB genetio class Profue: 12545578.dc 		-5012-00c04f	1		Log Level: Info	•
Language: Mearing Taglish . 200-01-15-101/7222.15.564 math.us 200-01-15-101/7222.15.564 math.us 200-01-15-101/77.34.7394 math.us 200-01-15-101/77.34.7394 math.us 200-01-15-101/77.34.7394 math.us 200-01-15-101/77.34.7397 math.us 200-01-15-101/77.34.8397 math.us 200-01-15	firmware messio device.cpp[180 device.cpp[180 device.cpp[180 device.cpp[180 device.cpp[186 device.cpp[239 device.cpp[239	n.opj 160) Navi2001 herit000 is resond reso-copj 121) Vivi000001 herit00000 1 Naviature: MARA 1 Product Amire 1000 1 Secial Market 122450708JC 1 March Mode 1 March Mode 1 March Mode	5475338C4 (e5e3ef10-6530-3142	-5012-00c042	1		Log Level: Info	•
Lungeng: Merricu. India to 1 200-01-15-10:27:22.5564 auko au 200-01-15-10:27:24.554 auko au 200-01-15-10:27:34.729 auko au 200-01-15-10:27:34.859 auko au 200-01-15-10:27:34.859 auko au 200-01-15-10:27:34.859 auko au 200-01-15-10:27:34.859 auko au 200-01-15-10:27:34.859 auko au	o firmware sessio device motion device.copp 110 device.copp 130 device.copp 190 device.copp 190 device.copp 195 device.copp 235 device.copp 460 device.copp 640	 cpp[146]; has124001.hs/120001 is reserved; whole cpp[121]; \\\\U000000000000000000000000000000000	Log	140500-1108	1		lag level: Info	•
Language: Merrica. Radiato 30-0-1-15-10:27:22.556: anda. au 20-0-1-15-10:27:22.556: anda. au 20-0-1-15-10:27:24.754: anda. au 20-0-1-15-10:27:34.754: anda. au 20-0-1-15-10:27:34.877: anda. au 20-0-1-15-10:27:34.877: anda. au 20-0-1-15-10:27:34.877: anda. au 20-0-1-15-10:27:34.877: anda. au 20-0-1-15-10:27:34.877: anda. au 20-0-1-15-10:27:34.877: anda. au	firmware mention device_monitor_ device_copp[100 device_copp[100 device_copp[100 device_copp[100 device_copp[100 device_copp[252 device_copp[640 device_copp[640 device_copp[640	a.000 1863; BasT24003, DevT24003 is reaswedt winds rep (131); V.V.0000 PL, 233-878, 0001233- 10 Froident Samelins 100 Sequencies of the 10 Froident Dates 10 Sequencies 10 Sequencies of the 10 Froident Dates 10	Log	-5017-506047	9531ed)		kag keval: <u>Inte</u>	•
Languar: Marrian Indian -	firmare sealo device gotto device opp 110 device opp 110 device opp 120 device opp 235 device opp 235 device opp 646 device opp 646 device opp 646	 a.cop(184); Ras12401; Dev174000 is searced a.cop(184); Ras12401; Dev17400; Ras10, Ov91220 a.cop(184); Ras1240; Ras10, Ov91220; Ras10, Ov9124; Ras10	Log	-5017-00-041	a901ed)		Lag Laval: <u>Tafe</u>	•
Largeoret Merrica Ludith - 20-03-15-10/27/27.5554 anns ar 20-03-15-10/27/27.5554 anns ar 20-03-15-10/27/27.514.1894 anns ar 20-03-15-10/27/34.1894 anns ar 20-03-15-10/27/34.1897 anns ar	firmware mentio device_monitor_ device.opp[100 device.opp[100 device.opp[20 device.opp[20 device.opp[20 device.opp[40 device.opp[40 device.opp[40 device.opp[40 device.opp[40 device.opp[40]	angi 1551 Australia artistato i reamandi Martini (1211 - V.V.1004778,833478,00011324 17 Australia (1237) - V.V.1004778,833478,00011324 18 Oscial Number: J.2545078826 19 Oscial Number: J.2545078826 19 Oscial Number: J.2545078826 19 Oscial Number: J.2545078826 19 Oscial Number: J.2545078826 10 Oscial Number: J.255078826 10 Oscial Number: J.255078826 10 Oscial Number: J.25507826 10 Oscial Number: J.2550	Log	-501-506-910	1		kag kaval: <u>Info</u>	•
Improver Marcrack Light - 1	firmeare sealo device appl 10 device appl 10 device appl 10 device appl 10 device appl 25 device appl 25 device appl 640 device appl 640	a.goj 186j; RasT24001, DwTT4900 is removed winds rep [13]; V.VIDSWP L23a-FT0_00011234 1 Fromes: L2460F100 TB section L33a-FT0_00011234 1 Fromes: L2460F1000 1 Factor L2460F10000 1 Factor L2460F10000 1 Factor L2460F10000 1 Factor L2460F100000 1	Log	-9012-996942	9551ed)		Lag Lavel: Info	•
Inserver Inserver 229-01-15-10:27.22.554 make us 239-01-15-10:27.23.554 make us 239-01-15-10:27.34.793 make us 239-01-15-10:27.34.793 make us 239-01-15-10:27.34.793 make us 239-01-15-10:27.34.793 make us 239-01-15-10:27.34.791 make us 239-01-15-10:27.34.871 make us 239-01-15-10:27.34.8	Stimmerre mession device, mession device, opp [100 device, opp [400 device, opp [400 device] [400 d	 cogi 1441 Malifeldi.devileledi ar reseved. cogi 1441 Malifeldi.devileledi ar reseved. Roundretterrer. 2008. Product Scott and the resevent constraints of the resevent constraints. Abdoot Kele Soctave X. Scott and the resevent constraints of the resevent constraints. Abdoot Kele Soctave X. Scott and the resevent constraints of the resevent constraints. Soctave X. Scott and the resevent constraints of the resevent constraints. Soctave X. Scott and the resevent constraints of the resevent constraints. Soctave X. Scott and the resevent constraints of the resevent constraints. Soctave X. Scott and the resevent constraints. Soctave X. Scot	Log	340500-2102-	1		Lag Loval: Info	•
Despension Despension 2010 1-1-1 10 22.2.5.5.4 adds, a	firmenre sessio device specific d	angl 1011 Martigett information is measured. angl 1011 VIV00070, 0554720, 0504720, 0504720 Angl 2011 VIV00070, 0554720, 0504720 Angl 2012 VIV00070, 0554720, 0504720 Angl 2012 VIV00070, 0554720, 05047 Angl 2012 VIV00070, 0554720, 05547 Angl 2012 VIV0070, 0554720, 05547 Angl 2012 VIV0070, 0554 Angl 2012 VIV0070, 055	Log	-5012-00-042	951ed)		Log Loval: Info	•
Description Descriptin Descriptin Descriptin Descriptin Descriptin	b firmware semilar device semilar. device semilar device semila	n.ege(154) hasteletti. hastele	Log	100500-1100	9951ed)		ing Lovel: Title	•
Compared in the second region of the second re	firmure pessio device messio device mession device.upp180	a.gej 1441 huiziest. hviziesta a reasoner Milion ang 1211 huiziest. 1000 mar 1211 huiziest. 1000 mar 1210 huiziest. 1000 mar 1200 mar	Log	-9012-90c042	9951ed)		ing Level: (116	•
Laprace: Manual Antioned Indianed Manual Antioned	Cirmerre mession device, special device, speci		Log	-9016-91604	1		ing lovel: Into	•
Berner Market All All All All All All All All All Al	2 firmere estat derive entry derive entry	and 1411 holiototikaribidi ir manadi Andri Ali holiototikaribidi ir manadi Antonia antoni	Log	140503-1102	1		ing irrel: into	•